



Supplier/Subcontractor Check Sheet (MSN/DSN) & Record of Assessment

Supplier/Subcontractor: Safe Air Limited **Phone No:** 64 3 572 7776

Address: PO Box 244 Blenheim Marlborough, New Zealand **Fax No:** 64 3 572 7657

Services Provided to AA: AP3C and C-130J Component Repairs, Heat Treatment, Machining, Electroplating. **Email:** murray.oakenfull@safeair.co.nz

Nominated Contact(s): Murray Oakenfull

Audit Date(s): 7-May-12

Assessment	Initial	Re-assessment
Approval Recommended	YES	NO

Do the Services include:

Engineering Services	YES	NO
Maintenance Services	YES	NO

Assessment Conducted By: Anthony Bannister-Tyrrell
Peter Ellison

Assessment Endorsed By ^{Note 2:}
Anthony Bannister-Tyrrell

Appointment: *SMM*  Quality Manager

Appointment: SMM P3 Orion

Signature:  Date: 5-Jun-12

Signature:  Date: 5-Jun-12

- Notes:
1. In accordance with Procedure 54.3.1.1 para 7.4.2, tailor the make up of this check sheet to meet the scope of the assessment. This can be done by selecting the appropriate audit scenarios contained in this check sheet.
 2. In accordance with Procedure 54.3.1.1 para 7.6 and 7.7, if the scope of the contractor's services include maintenance or engineering then the Senior Maintenance Manager or the Senior Design Engineer must endorse the assessment.